

**PCN Number:** 02/2015  
**Release date:** January 20<sup>th</sup> , 2016  
**Title:** Firmware Update  
**Contact:** Basler Support  
**Type of Change:**  
 **Miscellaneous**    **Firmware**    **PC Software**  
 **Product design**    **Process**

### Affected models and expected first production / shipping date

Series	Model	Part Number	Production /shipping Date
Ace GigE	acA1300-60gmNIR	106202	08.12.2015
Ace GigE	acA1300-60gmNIR CS-Mount	106585	08.12.2015

### Change Description

With revision 106202 – 17 the model acA1300-60gmNIR gets a new firmware version.

### Reason for Change

The firmware change was necessary to adapt the sensor behavior especially the saturation capacity due to production variation of the sensor manufacturer, but we make sure that it is within our camera test specification.

Due to production variation of the sensor manufacturer – especially at the production of the silicon for sensors – it could come to minimal deviation of sensor behavior. This could appear at lower saturation capacity or blooming effect at long exposure times and high gain on the other hand.

Basler optimize this sensor behavior with the new firmware to deliver the familiar quality at its best.

---

#### Basler AG

##### Europe, Middle East, Africa

Tel. +49 4102 463 515

Fax +49 4102 463 599

support.europe@baslerweb.com

[www.baslerweb.com](http://www.baslerweb.com)

##### The Americas

Tel. +1 610 280 0171

Fax +1 610 280 7608

support.usa@baslerweb.com

##### Asia-Pacific Region

Tel. +65 6367 1355

Fax +65 6367 1255

support.asia@baslerweb.com

## Additional Information

Basler may make changes to specifications and product descriptions at any time, without notice. The information in this document is subject to change without notice.

---

**Basler AG**  
**Europe, Middle East, Africa**

Tel. +49 4102 463 515  
Fax +49 4102 463 599

[support.europe@baslerweb.com](mailto:support.europe@baslerweb.com)

[www.baslerweb.com](http://www.baslerweb.com)

**The Americas**

Tel. +1 610 280 0171  
Fax +1 610 280 7608

[support.usa@baslerweb.com](mailto:support.usa@baslerweb.com)

**Asia-Pacific Region**

Tel. +65 6367 1355  
Fax +65 6367 1255

[support.asia@baslerweb.com](mailto:support.asia@baslerweb.com)