Mannheim, July 1st 2018

Product Discontinuation Notice

Ref: microEnable IV x1 (Gen1) frame grabber

Dear Silicon Software customer, partner and/or distributor,

we would like to kindly inform you, that Silicon Software will discontinue the following products:

microEnable IV x1 (Gen1) frame grabber products

- microEnable IV AS1-PoCL (article no. 101624)
- microEnable IV AD1-CL (article no. 101630)
- microEnable IV AD1-PoCL (article no. 101634)
- microEnable IV AD1-mPoCL (article no. 101636)
- microEnable IV VD1-CL (article no. 101660)
- microEnable IV VD1-CB (article no. 101580)
- microEnable IV VD1-CL TRG180 (article no. 101581)
- (all customized bundles based on mE IV x1 boards)

Last time buy (LTB) is: 2019, July 1st
Last shipment (LTS) is: 2020, July 1st

Please note that the support for microEnable IV x1 (Gen1) frame grabbers will be continued for up to five years from LTB date.

We regret for any inconvenience caused. Silicon Software sales, distribution and marketing team stand at your disposal to assist

you in placing your company's final orders and/or in providing information about the replacing product s.

As replacement product we recommend marathon Camera Link frame grabber boards, **microEnable 5 ACL** (article no. 150601) and **microEnable 5 VCL** (article no. 150621)[1]. These Camera Link frame grabber boards support image acquisition from simultaneous Base Camera Link cameras, as well as single Base, Medium and Full configurations. Power over Camera Link (PoCL) is supported.

For additional information of the replacement product please refer to our documentation.

In case of questions we kindly encourage you to contact your Silicon Software sales person in charge in due time.

Dr. Klaus-Henning Noffz
Managing Director

SILICONSOFTWARE GmbH

Uta Mersiowsky
ProductManager

SILICONSOFTWARE GmbH

---

[1] Acquisition and processing extensions (PixelPlant PX200e and CLIO 4 Full) are **not available** for the recommended replacement board.