

Silicon Software GmbH • Konrad-Zuse-Ring 28 • 68163 Mannheim • Germany

Silicon Software GmbH

Konrad-Zuse-Ring 28 68163 Mannheim Germany

Mannheim, January 1st 2019

CEO

Dr. Klaus-Henning Noffz

Fon +49 621 789 507-0 Fax +49 621 789 507-10 info@silicon-software.de https://silicon.software

Registered Headquarter: Mannheim Amtsgericht Mannheim HRB 7553 VAT/USt.-ID. DE 812438151

Commerzbank AG. Mannheim IBAN: DE 87 67040031 0620356600 BIC Code: COBADEFFXXX

DZ Bank, Frankfurt am Main IBAN: DE 34 50060400 0000140851 BIC Code: GENODEFF

Sparkasse Rhein-Neckar-Nord IBAN: DE 65 67050505 0038400550 BIC Code: MANSDE66

Product Discontinuation Notice

Ref: microEnable IV x4 Camera Link frame grabber

Dear Silicon Software customer, partner and/or distributor,

we would like to kindly inform you, that Silicon Software will discontinue the following products:

microEnable IV x4 Camera Link frame grabber products

- microEnable IV AD4-CL (article no. 101640)
- microEnable IV AD4-PoCL (article no. 101644)
- microEnable IV VD4-CL (article no. 101670)
- microEnable IV VD4-PoCL (article no. 101674)
- microEnable IV AD4-LVDS (article no. 101710)
- microEnable IV VD4-LVDS (article no. 101760)
- Clio 4 Full (article no. 101321)
- PixelPlant PX200e (article no. 101205)
- (all customized bundles based on mE IV CL/LVDS boards)

Last time buy (LTB) is: 2020, January 1st Last shipment (LTS) is: 2021, January 1st

Please note that the support for microEnable IV x4 frame grabbers and accessories will be continued for up to five years from LTB date.



We regret for any inconvenience caused. Silicon Software sales, distribution and marketing team stand at your disposal to assist you in placing your company's final orders and/or in providing information about the replacing product s.

As replacement product we recommend marathon Camera Link frame grabber boards, microEnable 5 ACL (article no. 150601) and microEnable 5 VCL (article no. 150621)¹. These Camera Link frame grabber boards support image acquisition from simultaneous Base Camera Link cameras, as well as single Base, Medium and Full configurations. Power over Camera Link (PoCL) is supported.

For additional information of the replacement product please refer to our documentation.

In case of questions we kindly encourage you to contact your Silicon Software sales person in charge in due time.

Dr. Klaus-Henning Noffz

Managing Director

SILICONSOFTWARE GmbH

Uta Mersiowsky ProductManager

SILICONSOFTWARE GmbH

¹ Acquisition and processing extensions (PixelPlant PX200e and CLIO 4 Full) are **not available** for the recommended replacement board.